

SAFETY ALERT

ENERGY
SAFETY
CANADA

UTILITY TASK VEHICLE ROLLOVER – NO INJURIES

Description

A utility task vehicle (UTV), also called an all-terrain vehicle, sustained extensive damage when it overturned in a ditch and caught fire.

To view the complete safety alert on the utility task vehicle rollover - no injuries, click [here](#).

To view all available safety alerts click [here](#).